# Permahyd® Hi-TEC **New e-Coat Parts Refinish Process**



#### Retrieve Color & Check Booth's Climate Conditions

Follow color retrieval SOP process

Prepare spray out panel to verify color match

Check booth's relative humidity (RH), adjusting booth temperature, if needed

### Clean & Inspect

Clean with Axalta Silicone Remover 200

Final clean with Axalta Silicone Remover 200, 210, or 220 Low VOC

Inspect e-coat surface for dents or defects

Sheet metal e-coat panels DO NOT need to be sanded prior to 2K Surfacer/Sealer application

## **Prepare Parts**

Remove any blemishes with P600 by hand or DA

Reclean thoroughly with silicone remover and scuff pad

SMC, fiberglass and plastic parts require sanding prior to wet-on-wet surfacer application



#### Apply Etch Primer & Sealer

Sealer is required on all new parts

Apply 1.5-2 coats of 410/4085 1K Primer, 420 or 425 2K Etch Primer to any bare metal areas

Allow proper flash time per TDS

Apply 1 medium coat of Spies Hecker® Permahyd® 2K Sealer 5650

Allow proper flash times per TDS



#### "One Touch" Process for Reassembly

Position the parts on stands as they fit on the vehicle

Follow 2-Stage or 3-Stage application SOP process

Refer to TDS for application & flash time



#### **Cut-in Process (Optional)**

Apply 1 medium coat of Spies Hecker® Permahyd® 2K Sealer 5650 to interior surfaces

Allow proper flash times per TDS

Apply color to interior according to 2-stage or 3-stage application SOP process

See TDS for under hood options



#### **Apply Color**

Follow 2-stage or 3-stage application SOP process



#### **Apply Clear Coat**

For most repairs:

- Apply 1.5 coats (elastified if on flexible parts) Permacron® Clear Coat 8180 or Permasolid® Clear Coat 8096 and bake per TDS

- Apply 2 coats (elastified if on flexible parts) Permasolid® Air Dry Clear Coat 8094 and bake for 15-30 minutes per TDS

#### spieshecker.us

