

technical data

Corroless S

Rust Stabilising Primer

Issue Date: June 2020 Code: LS00001/2 Page 1 of 2

Product Description	A general purpose, single pack, rust stabilising primer.								
Features & Use	 Over 30 years track record in corrosion control Excellent wetting properties Designed to penetrate firmly adhered rust Will withstand operating temperatures up to 200°C Ideal for general maintenance Contains Corroless Pigment Applications include, tank exteriors, jetties, bridges, street furniture and other structural steel NOT suitable for application onto galvanised steel 								
Approvals/ Certification	 NATO Stock Numbers: Corroless S1 H1 9010 99 220 3622 Corroless S2 H1 8010 99 220 3621 Sold on track record and customer recommendation 								
Finish	Low gloss								
Volume Solids	44% <u>+</u> 2%								
VOC Content	S1 : 310 <u>+</u> 20 g/litre S2 : 411 <u>+</u> 20 g/litre								
Film Thickness Range And Coverage		Dry Film Thickness		Wet Film Thickness		Theoretical Coverage			
	Typical	35 µm		80 µm		12.6 m ² /litre			
	Practical coverage depends on the application method, painting conditions and the shap and roughness of the surface to be coated								
Drying Times	Applied to 35	ed to 35 microns DFT		D₀C	+18ºC	+30°C			
	Dust Free		4	hr	2 hr	1 hr			
	Hard Dry		6	hr	4 hr	2 hr			
	Overcoating	ercoating Minimum Maximum		hr ays	4 hr	2 hr			
Colours	7days	3 days							
Mix Ratio	S1 - Red Brown S2 - Buff								
Pot Life	Single Pack								
SG	Not applicable								
	1.26 Store in dry, and conditions and protect from front								
Storage Conditions	Store in dry, cool conditions and protect from frost Minimum 24 months if stored as above in unopened containers								
Shelf Life									
Flash Point	Above 60°C								



Corroless S

	 If required due to obvious dirt/grease contamination or suspected salt or chemical contamination, clean all surfaces with a water-soluble degreaser, wash down with clean fresh water and allow to dry before commencing main preparation 								
Surface Preparation	Recommended substrate: Steel								
	• Manual Preparation: Prepare using rust scrapers, chipping hammers, needle guns, wire brushes etc. to St2 standard of ISO 8501-1:2007 or equivalent. Where necessary, remove weld spatter and grind smooth all sharp edges and weld seams. Wash down with clean fresh water and allow to dry before coating								
	• Mechanical preparation: Blast clean to minimum Sa1 standard of EN ISO8501-1:2007 or equivalent with a surface profile of 50 to 75 microns. Wash down with clean fresh water and allow to dry								
	New Steel: All mill scale must be removed prior to application								
	Before coating all surfaces should be firm, clean dry and free from oil, grease, powdery flash rusting and other contamination								
Mixing	Stir thoroughly before use								
Thinner / Cleaner	Corroless Thinners No.2 (Solvent Gun Wash may be used for cleaning only)								
Application Conditions	Only apply in conditions of good ventilation which must be maintained during drying and curing. Do not apply when rain, mist, sleet or snow are imminent. During application and drying time of the paint coating, the surface should be dry, the Relative Humidity should not exceed 90% and the steel temperature should remain at least 3°C above the dew point. Paint temperature should ideally be at a minimum of 15°C.								
Application Methods	Method	Airless Spray	Conventional Spray	Brush	Roller				
		Yes	Yes- thinning required	Yes	Yes				
	 Airless spray: output fluid pressure 3500-4000 psi, tip size 17-21 thou (0.43-0.53mm). For detailed advice contact Corroless Conventional Spray An addition of up to 10% Corroless Thinners No.2 will be required Brush: apply unthinned, lay on, do not over brush. When rollering, use a short nap lamb's wool roller and a maximum addition of 5% Corroless Thinners No.2. Lay off with a brush to complete the finish 								
	Application Temperature: Range 2°C-35°C								
Product Notes	 Stripe Coating: Stripe coat all edges, nuts and bolts, welds etc. Overcoating: Overcoat with itself Corroless SHB, or Corroless RF16. If overcoating time is exceeded and contamination has occurred, clean using a detergent solution/fresh water and allow to dry before continuing If maximum overcoat times are exceeded abrade the surface and wash down with fresh water to remove contamination and allow to dry before continuing 								
Health & Safety	Containers are provided with safety labels which should be observed. Further information about hazardous influences and protection are detailed in individual Product Safety Data Sheets. A Safety Data Sheet for this product is available on request from Axalta Coating Systems.								



AN AXALTA COATING SYSTEMS BRAND

The information provided herein corresponds to our knowledge on the subject at the date of its publication. This information may be subject to revision as new knowledge and experience becomes available. The data provided fall within the normal range of product properties and relate only to the specific material designated; these data may not be valid for such material used in combination with any other materials or additives or in any process, unless expressly indicated otherwise. The data provided should not be used to establish specification limits or used alone as the basis of design; they are not intended to substitute for any testing you may need to conduct to determine for yourself the suitability of a specific material for your particular purposes. Since Axalta cannot anticipate all variations in actual end-use conditions Axalta makes no warranties and assumes no liability in connection with any of this information. Nothing in this publication is to be considered as a license to operate under or a recommendation to infringe any patent rights. This product is for professional use only.